







ACT State of the Environment Report 2011

Land and Water: Water quality indicator cluster paper




Annex 1

ACT Lakes Water Quality

Lake Tuggeranong water quality indicators









ACT State of the Environment Report 2011





ACT State of the Environment Report 2011

Lake Ginninderra water quality indicators









ACT State of the Environment Report 2011






ACT State of the Environment Report 2011

Point Hut Pond water quality indicators









ACT State of the Environment Report 2011





ACT State of the Environment Report 2011

Gungahlin Pond water quality indicators







ACT State of the Environment Report 2011





ACT State of the Environment Report 2011

ACT Rivers and Creeks Water Quality



Murrumbidgee River water quality indicators



Note: the scale of the mg N/L data range differs from other sites due to higher reading values






ACT State of the Environment Report 2011






ACT State of the Environment Report 2011




Molonglo River water quality indicators



Note: the scale of the mg N/L data range differs from other sites due to higher reading values









ACT State of the Environment Report 2011






ACT State of the Environment Report 2011

Paddy's River water quality indicators









ACT State of the Environment Report 2011






ACT State of the Environment Report 2011

Gudgenby River water quality indicators









ACT State of the Environment Report 2011






ACT State of the Environment Report 2011

Ginninderra Creek water quality indicators









ACT State of the Environment Report 2011



ACT State of the Environment Report 2011

Queanbeyan River water quality indicators



ACT State of the Environment Report 2011

